



ALK-7-FP-101

QUICK START INSTRUCTIONS



CAP MOUNT FOR
VARIOUS APPLICATIONS.

Locate and separate
the hammerhead
bolts from the caps
and insert into upper
groove (detail 1).
Place graphic over
bolts (detail 2). Screw
caps back onto bolts
as shown.

