


Flat Screen Surface Mount Connection



Step1

Connect the **Accessory Brackets** and the **Tube Extenders** to the **Truss**. Note the orientation of the weld nuts on the **Tube Extender** is important. If the **Accessory Brackets** are not attached to the **Extender Tube**, do so.

Note: See the **Accessory Bracket Connection Detail** for further clarification on this connection.

Step2

Screw the **Joining Plate** to the **Tube Extender** using the provided **5/16-18 Bolts**. Bolt through the **Joining Plate** into the weld nuts on the **Tube Extender**.

Step3

The remaining hardware will be used to connect the monitor **Wall Mount Plate** to the **Joining Plate**.

41086

02/14/03



Member

7316 Aspen Lane North
Minneapolis MN 55428-1109

e mail: info@interlockstructures.com
web: www.interlockstructures.com

INTERLOCK
Interlock Structures International, Inc.

voice: 763.425.1464
800.468.1497
fax: 763.425.8205